


MONUMENT RECORD

STATE OF INDIANA~COUNTY OF MONROE

Section: 22, Township: 8 NORTH, Range: 1 WEST,


Monument Description & Remarks: 5/8" REBAR NO CAP FOUND

3" BELOW GRADE 1.9' NORTH OF CENTER LINE



I, Eric Lee Deckard, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 8th day of SEPTEMBER, 2004 A.D.
Completed by Steven V. Farkas, Monroe County Surveyor

Eric Lee Deckard
Indiana Registered Land Surveyor No. LS 29900012



MONUMENT RECORD
State of Indiana - County of Monroe

Section: 15


Township: 8 North

Range: 1 West

Corner ID: Per M-13


Monument Description & Remarks: Found 5/8" Rebar in centerline of Rhorer Road, at SW corner of section, 298' East of another rebar that was erroneously tied off by previous County Surveyor (reference attached letter and drawing).

References on file in the County Surveyor's Office: Letter and drawing from Michael Friley.



I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 2nd day of February, 1999.

Kevin P. Enright
Administered by Surveyor Review Board



FROM: Michael W. Friley
DATE: January 8, 1999
TO: Kevin Enright-Monroe County Surveyor
INRE: Northwest corner of Section 22, T8N, R1W

Kevin,

While surveying in this area recently I became aware that the above Section corner has been incorrectly tied off. The monument marked (A) on the enclosed Sherwood Estates Section I Plat was the corner incorrectly tied off. The proper corner is 298.7 feet east of monument A and is a 5/8 inch diameter rebar in the centerline of Rhorer Road. Confirmation of this corner was achieved by measuring its relationship to monuments found in the field and marked corners (B) and (C). It appears monument (A) has one of your chevrons painted on it. Thank you for your help in this matter.

Sincerely,



Michael W. Friley
Former Monroe County Surveyor

MONUMENT RECORD

Corner I.D. #


M-13

STATE OF INDIANA - COUNTY OF MONROE

Section Twenty-two, 22, Township 8 North, Range 1 West

Monument Description & Remarks: Found 5/8" Rebar 1" under surface, 1.9'

North of centerline of Rhorer Road, at NW corner of section. Rebar is in
line w/old woven wire fence to the North. Survey marker sign set (see below).



State of Indiana

County of Monroe

I, Michael W. Friley, County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; and the above data is given under my hand and seal this 17th day of April, 1996 A.D.

Space
Reserved For
Recording
Officer

Indiana Registered Land Surveyor No. _____ or

Monroe County Surveyor's Office

United States Government Agency

Monroe County Surveyor

Title

Field Book:

96-01

Page:

39

